

FIGURE 6. MEASURED SECTIONS IN OUTCROPS OF THE LIGNITE CREEK AND SUNTRANA FORMATIONS IN THE VALLEY OF LIGNITE CREEK.

#568

R 3

REPORT QE 75 OGS no. 73-355
GEOPHYSICAL INSTITUTE LIBRARY
UNIVERSITY OF ALASKA